



Tech Info Library

Apple IIe and the Numeric Keypad: Some problems

Revised: 5/25/89
Security: Everyone

Apple IIe and the Numeric Keypad: Some problems

=====

If an Apple IIe is configured with a 342-0132-B ROM as the keyboard ROM, then the numeric keypad works properly. If there is a 342-0132-C ROM installed, then the keypad numbers work right but the functions do not. This ROM IS NOT related to the Mousetext ROM change. A Rev D ROM will be released soon.

Apple Technical Communications

Tech Info Library Article Number:883